


<b>EASA</b>	<b>EMERGENCY AIRWORTHINESS DIRECTIVE</b>
	<b>AD N° : 2005-0016 Rev 1</b>  <b>Issued/Date:</b> 20 April 2005

No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.

<b>Type Approval Holder's Name</b>	<b>Type/Model designation</b>
E. Marganski i Wspolnicy Zaklady Lotnicze	Swift S-1
TCDS Number: ULC BG-181	
Foreign AD No: N/A	
Supersedure: This EASA AD supersedes D-2005-154R1 dated 11 April 2005	

<b>ATA 27 - Control Column and Stop in Elevator Control Circuit - Inspection</b>
--

<b>Manufacturer:</b>	E. Marganski i Wspolnicy Zaklady Lotnicze
<b>Applicability:</b>	All Swift S-1 sailplanes
<b>Reason:</b>	<p>Cracked welded joints have been found at the attachment points of the control column P/N A/2-1.00.200 left of the control stick in the elevator control system. In addition, it is necessary to inspect the elevator circuit control stops at the control column for correct installation and rectify if necessary.</p> <p>This EAD was revised to correct the EASA approval number.</p>
<b>Approval number, date</b>	2005-3709 dated 20 April 2005
<b>Effective Date:</b>	18 April 2005
<b>Compliance:</b>	<p>Before next flight:</p> <p>Inspect and if necessary exchange or/and modify the control column in accordance with instructions in manufacturer's Mandatory Service Bulletin Nr BO-112/2005 SWIFT S-1.</p>

<b>Ref. Publications:</b>	<p>Zaklady Lotnicze Mandatory Service Bulletin Nr BO-112/2005 SWIFT S-1 dated 24 January 2005.</p> <p>Copies may be obtained from:</p> <p>E. Marganski i Wspolnicy Zaklady Lotnicze Spolka Komandytowa ul. Strazacka 60 43-382 Bielsko-Biala Poland</p>
<b>Remarks</b>	<p>The manufacturer's service bulletin required action before 31 March 2005; and as this AD is issued after this date, compliance is as set as above. This EASA AD was preceded by an LBA AD. As an Emergency AD, there has been no consultation.</p> <p>Enquiries regarding this Emergency Airworthiness Directive should be referred to: Mr Roger hardy, EASA Certification Manager General Aviation; <a href="mailto:roger.hardy@easa.eu.int">roger.hardy@easa.eu.int</a>.</p> <p>EASA Postfach 101253 D-50452 Köln Germany</p>